

## Level 2

|  |   |
|--|---|
| Straight and Corner Cape chisels               | <a href="https://www.youtube.com/watch?v=ERm5qwZ9AsI&amp;ab_channel=ChristCenteredIronworks">https://www.youtube.com/watch?v=ERm5qwZ9AsI&amp;ab_channel=ChristCenteredIronworks</a> |
| Making a heading plate for bottom tools        |   |
| Transmogriifier (Final hammer eye drift)       | <a href="https://www.youtube.com/watch?v=BZqLqaSkmyc&amp;ab_channel=FriisForge">https://www.youtube.com/watch?v=BZqLqaSkmyc&amp;ab_channel=FriisForge</a>                           |
| Spring Fuller                                  | <a href="https://www.youtube.com/watch?v=am0Xijq1i2c&amp;ab_channel=WorkingWithIronNathan">https://www.youtube.com/watch?v=am0Xijq1i2c&amp;ab_channel=WorkingWithIronNathan</a>     |
| Box tongs (draw out or forge-weld reins)       | <a href="https://www.youtube.com/watch?v=Qf1n9U-lp78&amp;t=3s&amp;ab_channel=MarkAspery">https://www.youtube.com/watch?v=Qf1n9U-lp78&amp;t=3s&amp;ab_channel=MarkAspery</a>         |
| Scrolling wrench (case hardening)              | <a href="https://www.youtube.com/watch?v=nvFuwXUyJ8A&amp;ab_channel=MarkAspery">https://www.youtube.com/watch?v=nvFuwXUyJ8A&amp;ab_channel=MarkAspery</a>                           |
| Scrolling Tongs (draw out or forge-weld reins) | <a href="https://www.youtube.com/watch?v=jp6lQ8fkrUU&amp;t=1036s&amp;ab_channel=MarkAspery">https://www.youtube.com/watch?v=jp6lQ8fkrUU&amp;t=1036s&amp;ab_channel=MarkAspery</a>   |
| Leafing hammer                                 | <a href="https://www.youtube.com/watch?v=z7XWKITVXMs&amp;t=21s&amp;ab_channel=MarkAspery">https://www.youtube.com/watch?v=z7XWKITVXMs&amp;t=21s&amp;ab_channel=MarkAspery</a>       |
| Scroll form                                    | <a href="https://www.youtube.com/watch?v=ieZAeG9oDjI&amp;ab_channel=BlackBearForge">https://www.youtube.com/watch?v=ieZAeG9oDjI&amp;ab_channel=BlackBearForge</a>                   |
| Ribbon scroll                                  | <a href="https://www.youtube.com/watch?v=39-hEXUb26k&amp;ab_channel=BlackBearForge">https://www.youtube.com/watch?v=39-hEXUb26k&amp;ab_channel=BlackBearForge</a>                   |
| Fish tail scroll                               | <a href="https://www.youtube.com/watch?v=OsjXOhQDtAI&amp;ab_channel=WorkingWithIronNathan">https://www.youtube.com/watch?v=OsjXOhQDtAI&amp;ab_channel=WorkingWithIronNathan</a>     |
| Half Penny scroll                              | <a href="https://www.youtube.com/watch?v=8oyi0FHZMWE&amp;ab_channel=BlackBearForge">https://www.youtube.com/watch?v=8oyi0FHZMWE&amp;ab_channel=BlackBearForge</a>                   |
| Beveled Scroll                                 | <a href="https://www.youtube.com/watch?v=khtCFCDWAfk&amp;ab_channel=SchmiedekunstMiller">https://www.youtube.com/watch?v=khtCFCDWAfk&amp;ab_channel=SchmiedekunstMiller</a>         |
| Collars  | <a href="https://www.youtube.com/watch?v=aI0l1UPFCBc&amp;ab_channel=DF-InTheShop">https://www.youtube.com/watch?v=aI0l1UPFCBc&amp;ab_channel=DF-InTheShop</a>                       |
| Hardy tools (Bottom swage) (case hardening)    | <a href="https://www.youtube.com/watch?v=09w5N5BCumA&amp;ab_channel=ABANAorg">https://www.youtube.com/watch?v=09w5N5BCumA&amp;ab_channel=ABANAorg</a>                               |
| Forge-welding (lap or drop tong weld)          | <a href="https://www.youtube.com/watch?v=OjDugWCp3-Q&amp;t=51s&amp;ab_channel=MarkAspery">https://www.youtube.com/watch?v=OjDugWCp3-Q&amp;t=51s&amp;ab_channel=MarkAspery</a>       |